

**THE CHANNEL EVOLUTION
MODEL (CEM), CHANNEL
INCISION, ENVIRONMENTALLY
COMPATABLE GRADE
CONTROL,
GC BUT NO BANK
STABILIZATION,
& SYSTEM-WIDE GC**



Track hoe

**MY PERSONAL
HEADCUT
WORKING ITS
WAY TOWARD
MY HOUSE**

SETTING THE STAGE FOR THE HARTMAN DITCH HEADCUT VIDEO

Note height of soil. THIS STARTED THE EXCITEMENT!!!



CONSTRUCTION – HARTMAN DITCH-REACH #1 - DERRICK 9-20-2012

Headcut moved upstream & underneath the bridge in minutes!



CONSTRUCTION – HARTMAN DITCH-REACH #1 - DERRICK 9-20-2012

**SHOW THE
HARTMAN
DITCH
HEADCUT
VIDEO**


Channel Evolution Model (Schumm, et al. 1984)

Originally developed to describe erosion evolution of Oaklimiter Creek, Calhoun City/Derma, MS.

A location-time substitution conceptualization is used to generate a five-reach type incised channel evolution model

In an idealized stream Types I-V will occur in sequence (series)

Channel Evolution Model



Channel Evolution Model


Type I Reach Characteristics

Type I reaches are generally characterized by a U-shaped cross section with little or no sediment stored in the channel bed.


Type I reaches are located upstream of the actively degrading reach and have not yet experienced significant bed or bank instabilities.

From C. Watson

INCISED CHANNEL EVOLUTION PHASES



Type I is upstream of active incision



$h_c = \text{CRITICAL BANK HEIGHT}$

Stream connected with its floodplain, bed stable

CEM Type I



Channel Evolution Model Type II

Reach Characteristics


Immediately downstream of Type I reaches, Type II reaches are encountered. Bed degradation is the dominant process in the Type II reach.

Type II channels are steepened reaches where the sediment transport capacity exceeds the sediment supply.


Although the channel is actively degrading in a Type II reach, the bank heights (h) have not exceeded the critical bank height (h_c). Therefore, banks are not geotechnically unstable.

From C. Watson

INCISED CHANNEL EVOLUTION PHASES



Type II reaches are actively incising, although mass wasting of bank has not been initiated ($h < h_c$)



$h_c = \text{CRITICAL BANK HEIGHT}$

**A large knickpoint, Niagara Falls (American Falls)
(This headcut moves on average 2.5 ft per year)**




**Hard Dolomite
overlaying weaker
Rochester Shale,
could result in a
large riffle over time**

Dewatered American Falls, 1969

**So much rock fell that the Corps
dewatered the American Falls in
1969 to see what was going on!!**


Derrick 6-5-2009



**A headcut has to move
upstream over time
(toward the headwaters
of the stream), if the
waterfall does not move,
it is not a headcut!!!**

CEM Type II

**Headcut moving
upstream on
Johnson Cr, MS.**



Typically knickpoints will not occur in non-cohesive materials (sands, etc.).

Sand will not stand vertically with water flowing over it.

CEM Type II

**A series
of small
headcuts**





**Dr. Watson with
large headcut in a
CEM Type II
stream, Johnson
Creek, MS. Banks
bad upstream**

**Looking US at a North Miss. stream, CEM Type II
upstream (downcutting) & Type III (almost immediately
twice as wide) in foreground.**



Channel Evolution Model

Type III Reach Characteristics


As bed degradation continues, the bank heights and angles will continue to increase.

When the bank heights have exceeded the critical bank height for stability, mass failures (geotechnical instability) begin to occur in the Type III reaches.


The dominant process in the Type III reach is channel widening.

From C. Watson

INCISED CHANNEL EVOLUTION PHASES



In the Type III reach, mass wasting of the banks with rapid channel widening is the dominant process



$h_c = \text{CRITICAL BANK HEIGHT}$

CEM Type III, rapid over widening of stream





**CEM Type III-
bridges too short**

CEM Type III
Bellefontaine Creek,
{sand & clay bed, rural,
slope <1%} April 2005,
rapid widening




Bellefontaine Creek about 700 ft US of the previous picture. CEM Type II, but the headcut is coming, followed by channel widening



**HEADCUTS
GONE BAD!!**


**Headword migration of
knickpoints stopped by twin
road culverts, north MS.**



A vehicle

CEM Type III

Las Vegas Wash, NV. has degraded from a 1 ft deep by 100 ft wide channel in 1975, to a 40 ft deep by 1,000 ft wide channel in 1995!!



**Huge problems with
perchlorate
interception from the
groundwater table**


**I am standing on the roots of
dead wetland plants, over
2,200 acres of wetlands lost**

Photo by Pat A. Glancy, U.S. Geological Survey

Upstream view of Las Vegas Wash from Northshore Road on May 15, 1975

Then

2,400 Acres of Wetlands



Channel Evolution Model


Type IV Reach Characteristics

The Type IV reaches are downstream of the Type III reaches and represent the first manifestation of the incised channel returning to a new state of dynamic equilibrium.


In the Type IV reach, geotechnical bank instabilities and channel widening may continue, but at a much reduced rate.

From C. Watson

INCISED CHANNEL EVOLUTION PHASES



Channel widening continues at a much reduced rate in the Type IV reach. The first manifestation of a new equilibrium emerges.



$h_c = \text{CRITICAL BANK HEIGHT}$

CEM Type IV, MS., should be a single-thread channel





CEM Type IV, Illinois

Channel Evolution Model


Type V Reach Characteristics

Type V reaches represent a state of dynamic equilibrium with a balance between sediment transport capacity and sediment supply.


Bank heights in the Type V channel are generally less than the critical bank height, and therefore, geotechnical bank instabilities do not exist.

From C. Watson

INCISED CHANNEL EVOLUTION PHASES



Type V reaches represent a state of dynamic equilibrium with a balance between sediment supply and sediment transport capacity.



h_c = CRITICAL BANK HEIGHT

Old floodplain bench (hundreds of feet wide) is now a disconnected terrace



New floodplain bench 6 ft wide

**CEM Type V, Middle Fork
Worsham Cr. Duck Hill, MS**

**CONCEPTUALLY,
STABILIZE
HEADCUTS FIRST,
THEN WORRY
ABOUT BANK
INSTABILITY SECOND**

**GRADE CONTROL SHOULD
BE LOCATED IN STRAIGHT
REACHES BETWEEN BENDS.**

**LUNA LEOPOLD SAYS
SPACING SHOULD BE 5 TO
7 BANKFULL CHANNEL
WIDTHS APART**

(ideally with a bend in between)

**WELL-GRADED
LOOSE STONE
ENGINEERED
ROCKED
RIFFILES (ERR)**

**WAYNE KINNEY'S REALLY
TALL ENGINEERED
ROCKED RIFFLES (ERR)
CASE STUDY: ERR #12,
WHICH IS A 4.7 FT TALL
STRUCTURE
Big Creek, Carbondale area, IL.**

**A 4.7 ft tall ERR, Big Creek, Union
County, IL. {rural, sand-gravel, pool-
riffle-pool, meandering, incised}
Designed by Wayne Kinney**

Mini case study: 2 of 10



**Looking DS at the 4.7 ft tall
Engineered Rocked Riffle
in the proper location in the
crossing between two bends**

**Photo by Derrick
2/7/2007**

Great info on Robert Newbury Rocked Riffles

- <http://ouc.collegestoreonline.com/>
- <http://www.newbury-hydraulics.com/workshops.htm>
- Bob Newbury's out-of-print "Stream Analysis & Fish Habitat Design Manual" is available at <ftp://ftp.lgl.com/pub/> under 'Stream Analysis.pdf'

When building a series of Newbury RR Bob always puts a NRR "at grade" (buried) at the DS end of the project to protect against DS headcuts, max height of a NRR is 1.5 ft, & **Bob always puts a tailwater of 1/3 the height of the upstream NRR on the upstream NRR. This provides energy dissipation into the tailwater pool, but also provides sediment continuity (sediment does not deposit between NRR's & stream does not meander & flank the DS NRR)**

Bank protection

Key

Pool


**←
ERR**

Glide

Pool

Bank protection

Key



A 4.7 ft tall ERR, Big Creek, Union County, IL. Designed by Wayne Kinney


Mini case study: 4 of 10



Key is dug 3 ft deep into substrate & up each bank. Stone is IL-DOT RR5-well-graded stone with a top size of 400 pounds.

**Photo by Derrick
2/7/2007**

AN ENGINEERED ROCKED RIFFLE




Use well-graded, self-adjusting stone. Bigger stone is better.

Choke stone so all flow goes over the top (not through) the ERR. Upstream face is in **compression** (due to water flow), so smaller stone or spawning gravel can be used. Slope might have to be flatter for some spawning species.

AN ENGINEERED ROCKED RIFFLE

Greatest shear stress is on upper
 $\frac{1}{6}^{\text{th}}$ of this downstream slope



Newbury says the backwater should be $\frac{1}{3}$ the total height of the structure to dissipate energy, & also pass sediment through the system.

A 4.7 ft tall ERR, Big Creek, Union County, IL. Designed by Wayne Kinney

Mini case study: 5 of 10



Looking DS. Uniform 20 to 1 slope, roughness dissipates energy & assists in fish passage.

**Photo by Derrick
2/7/2007**

**A 4.7 ft tall ERR, Big Creek, Union
County, IL. Designed by Wayne Kinney**

Mini case study: 6 of 10

**Photo by Derrick
2/7/2007**



**Flood flow crested 5 ft above
banks (30 ft over the crest of
the ERR) with no damage**

**A 4.7 ft tall ERR, Big Creek, Union
County, IL. Designed by Wayne Kinney**

Mini case study: 7 of 10



**Looking US at the
4.7 ft tall Engineered
Rocked Riffle**

**Photo by Derrick
2/7/2007**

**A 4.7 ft tall ERR, Big Creek, Union
County, IL. Designed by Wayne Kinney**

Mini case study: 8 of 10



**Photo by Derrick
2/7/2007**



Looking US. A thing of beauty!! Stone was track-walked in to increase stability

**Photo by Derrick
2/7/2007**

**A 4.7 ft tall ERR, Big Creek, Union
County, IL. Designed by Wayne Kinney**

Mini case study: 10 of 10



**Looking US,
note riprap
bank protection.**

**Photo by Derrick
2/7/2007**

WHAT HAPPENS TO AN UNSTABLE STREAM WHEN ONLY GRADE STABILIZATION IS INSTALLED

**(no bank stabilization built, a
20 year long study)**


Long Creek Grade Control Case Study Near Batesville, MS

From Dr. Dave Biedenharn, BIEDENHARN GROUP, INC.

3303 Woodlands Place, Vicksburg, MS 39180 (cel) 601-529-4685

e-mail: BIEDENHARNGROUP@YAHOO.COM


Looking US at a typical section of incised, highly disturbed section of Long Creek (Channel Evolution Model Type 3). Nothing stable in this picture!!



Three ARS style sheet-pile low drop (4 to 7 ft tall) grade control structures were built over a long section of Long Creek



Comparative Thalweg Profile Long Creek Upstream of Low Drop Grade Control Structure



Long Creek Bank Evolution



After grade control was installed banks were stable for about 15 yrs, Dr. Dave says they should have stopped the study then !!!!



**Of course they did not, & after that period significant erosion occurred.
Why?? No one really knows, it appears to have crossed a threshold.
But they did get 15 years of bank stabilization for free!!**



**WHAT HAS HAPPENED
TO THE BED OF
PRAIRIE CREEK
(Washington, IN. area)
SINCE STRAIGHTENING
IN 1960?**


**COMPARING THE BED
PROFILES FROM 1963 &
2007 SHOW THAT THE BED
OF PRAIRIE CREEK HAS
DROPPED ANYWHERE
FROM 2 TO 9 FT,
DEPENDING ON LOCATION.**

PART OF THE PRAIRIE CREEK GRADE CONTROL PLAN

**(27 grade control
structures over 40 miles of
straightened stream)**


**A SYSTEM-WIDE
PROBLEM WILL
REQUIRE A
SYSTEM-WIDE
SOLUTION !!**

Red line is bed in 1963, black line is bed in 2007. Blue line is water surface after grade control structures (small dams) are installed



**ANALYSIS OF RATIOS OF
BED DEGRADATION VS.
INCREASE IN CHANNEL
WIDTH ON DIFFERENT
STREAMS NATIONWIDE
SHOWS THE RATIO TO
VARY FROM 1 to 5, to 1 to 22
(1 ft drop=22 ft wider channel)!!!!**


Red line is bed in 1963, black line is bed in 2007. Blue line is water surface after Rocked Riffle grade control structures are installed



$4.2 \text{ ft} \times 5 = 21 \text{ ft}$ wider channel

$4.2 \text{ ft} \times 22 = 92 \text{ ft}$ wider channel

Red line is bed in 1963, black line is bed in 2007. Blue line is water surface after Engineered Rocked Riffles (ERR) are installed



Downstream ERR backs water up
on the upstream $ERR = \frac{1}{3}$ total
height of the US $ERR \frac{4.2}{3} = 1.4$ ft

From Brian Winkley

MAINTENANCE ON ALLUVIAL RIVERS

1. Most Rivers Operating in a Sedimentary Environment, Develop Sinuous Channels That Look Like This:



MAINTENANCE ON ALLUVIAL RIVERS

**2. In An Effort to Drain Lands for Agriculture and Improve Flood Conveyance
Many Alluvial Channels Have Been
Straightened**



MAINTENANCE ON ALLUVIAL RIVERS

3. Straightening a Sinuous Channel Increases its Slope, Thus Giving it More Energy and the Result Has Often Been An Increase in Bank Caving and Other Problems That Require Intermittent or, in Some Cases Constant Maintenance. The Single Factor That Has Led to the Successful Operation of These Straightened Channels, Has Been to Combine the Good Points of Both the Sinuous and the Straight Channels



MAINTENANCE ON ALLUVIAL RIVERS

**4. This Combined Symbol Represents the
Only Successful Means of Maintaining Straight
Channels**



**This PowerPoint presentation was
developed & built by Dave Derrick.**

**Any questions or comments, call my
personal cell @ 601-218-7717, or
email @ d_derrick@r2d-eng.com**

Enjoy the information!!

Creative
Peyton
Rainer,
age 4

